

# PROBLEM Solver™ BULLETIN

www.moogproblemsolver.com

## Difficulty Sourcing All Axle Service Repair Parts

Various GM, Ford,  
and Dodge Trucks

### PROBLEM:

**Difficulty in finding parts necessary for complete repair on 60 Series axles**

- Difficulty for technicians and fleet repair facilities in finding sources for all of the parts necessary to do a complete repair on 60 Series axles.
- There are no provisions on the existing axle to allow camber angle changes.

### SOLUTION:

**MOOG® K6652, K992, K8832, K8833**

- MOOG's K6652, K8832 and K8833 provide upper and lower repair kits for 4WD 60 series axles, making MOOG the only complete repair solution in the aftermarket.
- The K992, eccentric camber-adjusting king pin provides camber alignment adjustments of  $-1-1/2^\circ$  to  $+1-1/2^\circ$ . The kit is easily adjustable for the life of the vehicle.



Description	Application	Replacement Part No.
4WD 60 Series Axle Service Kit	Chevrolet/GMC K30, V30, K3500 and V3500 1977-91	K6652
	Dodge Truck W200 and W250 1957-93. W300 and W350 1961-93	K992
	Ford F250 1972-79. F350 1979 and 1985-91	K8832
	Ford Trucks 1985-91	K8833

